Behoort bij BaZ nr 408/19 Belongs to NL NtM 408/19

Delete section 6.4.2 and replace by:

| 6.4.2 | Request for a pilot |
|-------|--|
| Who | All seagoing vessels compulsory to pilotage before entering the pilotage region (see also section 6.5.1.1 'Local pilotage') |
| То | Port authorities harbour of destination or local Pilot Service via agent (Electronic Data Interchange [EDI]); When EDI is not available/operational a pilot request has to be made via agent or master by other means of communication: |
| | Pilotage Vlissingen (destination Netherlands harbours) |
| | Telephone: +31(0)118 48 95 09 Telefax: +31(0)118 41 23 21 E-mail: scheldepilot@loodswezen.nl Website: www.loodswezen.nl |
| | Pilot Services (destination Antwerpen) |
| | Telephone: +32(0)32 320 229 GSM: +32 (0)476 580 149 Telefax: +32 (0)3 2 322 085 E-mail: orderpilot@loodswezen.be (via pilot cruising station Wandelaar) E-mail: scheldepilot@loodswezen.nl (via pilot cruising station Steenbank) Website: www.loodswezen.be |
| | Pilot Services (destination Gent) |
| | Telephone: +32 (0)92 505711 GSM: +32 (0)478 581 480 Telefax: +32 (0)92 516 321 E-mail: orderpilot@loodswezen.be (via pilot cruising station Wandelaar) E-mail: scheldepilot@loodswezen.nl (via pilot cruising station Steenbank) Website: www.loodswezen.be |
| | Pilot Services (destination coastal harbours Belgium) |
| | Telephone +32 (0)50 355 239 GSM +32 (0)478 582 110 E-mail orderpilot@loodswezen.be Website www.loodswezen.be |
| | Belgium Pilot Services (Vlissingen) |
| | Telephone +31 (0)118 424 540 GSM +32 (0)473 897 002 Telefax +31 (0)118 431 537 Website www.loodswezen.be |
| When | At least 6h before arrival at pilot cruising station; When a request for a pilot has been made more than 24h in advance, the request has to be confirmed at least 12h but at the latest 6h before arrival at the pilot cruising station; At least 1h before arrival at Wandelaar or Steenbank pilot cruising station on VHF Ch. 65 or 64 respectivily; A delay in arrival time of 1h or more should be reported; Canceling a pilot request has to be made inmediately. |