

## Verbeterblad voor HP1 bij BaZ nr 118a/23

Verwijder sectie 14.4.1.5 ETA en 14.4.2 Request for a pilot van pagina 296 en vervang door:

### Block for HP1 to NL Ntm 118a/23

Delete section 14.4.1.5 ETA en 14.4.2 Request for a pilot of page 296 and replace by:

14.4.1.5		ETA
Who		<ul style="list-style-type: none"><li>All vessels carrying dangerous cargo;</li><li>Special transports;</li><li>Vessels restricted in their manoeuvrability.</li></ul>
To		Centrale Meldpost Waddenzee Telephone: +31 (0)88 79 74 599 VHF Ch 04
What		Name vessel - call sign - nationality - type of vessel and GT - loa - width - draught - Lloyds number - harbour of destination - ETA - sailing plan - cargo specifications - confirmation 'Bill of loading' on board - number of crew/passengers on board.
When		<ul style="list-style-type: none"><li>ETA - 24h entering Waddenzee;</li><li>Unexpected circumstances within VHF - range.</li></ul>

14.4.2		Request for a pilot
Who		All vessels compulsory to pilotage.
To		Pilot Coördination Centre Noord Telephone: +31 (0)596 61 36 72 E-mail: lodicon@loodswezen.nl
What		A - B - I - J - O - T - U - X
When		<ul style="list-style-type: none"><li>ETA - 12h (pilot station near fairway buoy Westereems);</li><li>Deviations of more than 1h should be reported;</li><li>ETA - 4h before arrival contact Pilot Office Delfzijl/Eemshaven on VHF Ch 19.</li></ul>
Note		See also section 14.4.3 'Explanation of codes'.